


Ultrasonic Sensor Diffuse Mode Sensor RU70U-M18M-UP8X2-H1151

Type designation



., pe ace.ga	
Ident-No.	1610070
E	100
Function	Ultrasonic diffuse mode sensor
Range	100700 mm

DL170LLM18M_LID8Y2_H1151

Resolution 1 mm
minimum measuring range 100 mm
minimum switching range 10 mm
Ultrasound frequency 200 kHz
Repeat accuracy 0.15 % of full scale

Temperature drift $\begin{array}{ll} \text{1.5\% of full scale} \\ \text{Linearity error} & \leq \pm 0.5 \% \\ \text{Edge lengths of the nominal actuator} & 100 \text{ mm} \\ \text{Approach speed} & \leq 4 \text{ m/s} \\ \text{Pass speed} & \leq 2 \text{ m/s} \\ \end{array}$

Operating voltage 15...30 VDC Residual ripple 10 % U., DC rated operational current ≤ 150 mA No-load current Io ≤ 50 mA Load resistance \leq 1000 Ω Residual current \leq 0.1 mA Response time typical 117 ms Readiness delay 300 ms NO/NC, PNP Output function Switching output Output 1 Switching frequency 4.8 Hz Hysteresis ≤ 10 mm Voltage drop at I. $\leq 2.5 \text{ V}$ Short-circuit protection yes/ Cyclic Reverse polarity protection yes

Design	Threaded barrel, M18
Radiation direction	straight
Dimensions	63 x Ø 18 mm
Housing material	Metal, CuZn, Nickel-plated
Transducer material	Plastic, Epoxyd resin and PU foam
Electrical connection	Connector, M12 × 1, 5-wire
Protection class	IP67

yes

LED, Yellow

LED, Green

Ambient temperature -25...+70 °C
Storage temperature -40...+80 °C
Declaration of conformity EN ISO/IEC EN 60947-5-2
Vibration resistance IEC 60068-2
MTTF 281 years

MTTF note acc. to SN 29500 (Ed. 99) 40 $^{\circ}$ C

■ Smooth sonic transducer face

- Cylindrical housing M18, potted
- Connection via M12 x 1 male
- Temperature compensation


Blind zone: 10 cm
 Range: 70 cm
 Resolution: 1 mm
 Sonic cone angle: 16°

1 × switching output, PNP

Teachable settings

NO/NC programmable

Wiring Diagram




Functional principle

Ultrasonic sensors capture a multitude of objects contactlessly and wear-free with ultrasonic waves. It does not matter whether the object is transparent or opaque, metallic or non-metallic, firm, liquid or powdery. Even environmental conditions such as spray, dust or rain hardly affect their function.

The sonic cone diagram indicates the detection range of the sensor. In accordance with standard EN 60947-5-2, quadratic targets in a range of sizes ($20 \times 20 \text{ mm}$, $100 \times 100 \text{ mm}$) and a round rod with a diameter of 27 mm are used.

Important: The detection ranges for other targets may differ from those for standard targets due to the different reflection properties and geometries.

Sonic Cone



Switching state


Object detected

Wire breakage protection



Ultrasonic Sensor Diffuse Mode Sensor RU70U-M18M-UP8X2-H1151

Mounting instructions/Description



Setting the switching point

The ultrasonic sensor features a switching output with a teachable switching point. The green and yellow LEDs indicate whether the sensor has detected the object.

One switching point is taught. This must be within the detection range. In this operating mode the background is suppressed.

Easy-Teach

Connect the TX1-Q20L60 teach adapter between the sensor and connection cable

Place object at the end of the switching range Press and hold button for at least 2 s against Gnd After a successful teach-in, the green LED flashes at 3 Hz and the sensor runs automatically in normal mode.

To invert the output function, press and hold the button against the Ub for 2...7s

LED response

In standard operating mode, the two LEDs indicate the switching state of the sensor.

Green: Object within the detection range but not in switching range

Yellow: Object is within the switching range

Off: Object is outside the detection range or signal loss



Ultrasonic Sensor Diffuse Mode Sensor RU70U-M18M-UP8X2-H1151

Accessories

Type code	Ident-No.	Description	Dimension drawing
MW-18	6945004	Mounting bracket for threaded barrel sensors; material: Stainless steel A2 1.4301 (AISI 304)	5.5 9.5 44.5 1.8 7.9

Function accessories

Type code	Ident-No.	Description	Dimension drawing
TX1-Q20L60	6967114	Teach adapter for inductive encoders, linear position, angle, ultrasonic and capacitive sensors	8 o 4.5 o 15 M12 x 1