## 

hoods with 2 levers

inserts			page:
CD		40 poles + ⊕	70
CDD		72 poles +	79
CDS		27 poles +	-
CDSH		27 poles +	88
CNE		16 poles + @	112
CSE		16 poles +	-
CSH		16 poles + @	112
CSH S		16 poles +	124
CCE		16 poles + @	132
CMSH, C	MCE	6+2 (aux) poles +	138 - 139
CSS		16 poles +	150
CQE		32 poles + ⊕	170
CQEE		40 poles + ⊕	176
CP		6 poles + ⊕	178
CX	6/12,	6/36 and 12/2 poles + @	197 - 199
CX		4/0 and 4/2 poles +	200 - 201
MIXO		4 modules	262 - 317






description	part No.	entry Pg	part No	entry M	part No.	entry M
with levers and gasket, side entry, high construction, without adapter 1)					MFO 16 G40	40
with levers and gasket, top entry with levers and gasket, top entry, high construction with levers and gasket, top entry, high construction with levers and gasket, top entry, high construction	CHV 16 G CAV 16 G CAV 16 G29	21 21 29	MHV 16 G32 MAV 16 G25 MAV 16 G32 MAV 16 G40	32 25 32 40		
with levers and gasket, top entry, high construction, without adapter 1) with levers and gasket, top entry, high construction, without adapter 1)	CFV 16 G CFV 16 G29	21 29	MFV 16 G25 MFV 16 G32	25 32		
with levers and gasket, top entry, high construction, without adapter 1)					MFV 16 G40	40


CHV G (CAV G) and [CFV G],

MHV G (MAV G) and [MFV G]


<sup>1)</sup> enclosure without adapter, threaded on the body, to be used only with a complete cable gland.



## MFO 16 G40



## MFV 16 G40







insulating cable gland or fittings without gasket



cable gland with O-Ring gasket